
Motors with Binary Inputs

ECE 476 Advanced Embedded Systems

Jake Glower - Lecture #10

Please visit [Bison Academy](#) for corresponding lecture notes, homework sets, and solutions



Introduction:

Part of the fun of being an engineer is you build things.


- Motors let you build things that move
- Examples: valves, robotic arms, cars, etc.

Several type of motors exist

- Smaller motors often have digital inputs (this lecture)
- Larger motors often have analog inputs (next lecture)

This lecture looks at driving with a Pi-Pico

- Stepper Motors,
- Solenoids,
- Brushless Servo-Motors (using pulse-width), and
- Digital Servo Motors (using pulse width)





Stepper Motors

Stepper motors are a common type of motor

- These interface well with microcontrollers.

Actually 2-phase AC synchronous motors

- Input: a 2-phase AC sine wave (sine & cosine)
- The frequency sets the motor speed




What's inside a stepper motor?

Rotor:

- The thing that spins
- Permanent magnets
 - number varies
- North & South poles
 - two poles per magnet

Stator

- Attached to the case
 - (doesn't spin)
- Can attract the N or S pole
 - depends on the direction of current flow



Stepper Motors: Hardware


The hardware must allow current to flow both ways in each winding

- Sine waves are positive and negative


H-bridges are usually used to drive a stepper motor

- L298N from ebay and Amazon
- 5V to 35V operation
- Up to 2A per phase
- Max power = 25W
- About \$3 each (2024 prices)

Higher power H-bridges are also available



Connections to your Pico board are:



Four wires from the Pico needed to drive the stepper motor

Software & Stepping


If you approximate a sine wave with a square wave, the motor steps.

The number of steps per rotation depends upon the motor

- How many magnetic poles per rotation
- The ones in lab have 50 poles
 - 50 sine waves equals one rotation

It also depends upon how you approximate a sine wave:

- Full-Stepping
 - four steps per cycle
 - 200 steps per rotation,
- Half-Stepping
 - eight steps per cycle
 - 400 steps per rotation
- Micro-Stepping
 - more than eight steps per cycle



Software - Full Stepping

Approximate sine waves with square waves.


- On for one clock
- Off for one clock

Output two square waves

- sine & cosine

This results in 4 steps per cycle

- A - B - C - D - repeat
- reverse the order to spin the other way
- 200 steps per rotation



Full Stepping: Code

Output the sequence

- A - B - C - D
- repeat

Use a table with 8 entries

- One for each step

A	=	0001	=	1
B	=	0010	=	2
C	=	0100	=	4
D	=	1000	=	8

```
# Stepper Motor - Full Stepping

from time import sleep_ms
from machine import Pin

PA = Pin(16,Pin.OUT)
PB = Pin(17,Pin.OUT)
PC = Pin(18,Pin.OUT)
PD = Pin(19,Pin.OUT)

TABLE = [1, 2, 4, 8]

def Step(X):
    Y = TABLE[X % 4]
    PA.value( Y & 8 )
    PB.value( Y & 4 )
    PC.value( Y & 2 )
    PD.value( Y & 1 )

x = 0
for i in range(0,100):
    x += 1
    Step(x)
    sleep_ms(10)
```

Software - Half-Stepping

Approximate sine waves with square waves


- on for 3 clocks
- off for 1

Output two square waves

- Sine & Cosine

This results in 8 steps per cycle

- A, AB, B, BC, C, CD, D, DA
- repeat
- 400 steps per rotation



Half-Stepping Code

Use a table with 8 entries

- One for each step

A	=	0001	=	1
AB	=	0011	=	3
B	=	0010	=	2
BC	=	0110	=	6
C	=	0100	=	4
CD	=	1100	=	12
D	=	1000	=	8
DA	=	1001	=	9

```
# Stepper Motor - Half Stepping

from time import sleep_ms
from machine import Pin

PA = Pin(16,Pin.OUT)
PB = Pin(17,Pin.OUT)
PC = Pin(18,Pin.OUT)
PD = Pin(19,Pin.OUT)

TABLE = [1, 3, 2, 6, 4, 12, 8, 9]

def Step(X):
    Y = TABLE[X % 8]
    PA.value( Y & 8 )
    PB.value( Y & 4 )
    PC.value( Y & 2 )
    PD.value( Y & 1 )


x = 0
for i in range(0,200):
    x += 1
    Step(x)
    sleep_ms(10)
```

Micro-Stepping:

A third option is to use PWM to approximate a sine and cosine wave.

- This is termed *micro-stepping*.
- The number of levels per cycle is arbitrary

PWM allows any voltage from 0% to 100%



MicroStepping: 16 Steps per Cycle

Initialization of the three outputs

- Phase A
- Phase B
- Phase C

Each is a PWM output

- 100Hz
- Duty cycle will vary

Result is 800 steps per rotation

- 50 x 16

```
from machine import Pin, PWM
from time import sleep_ms
```

```
PA = Pin(16,Pin.OUT)
PA = PWM(Pin(16))
PA.freq(100)
PA.duty_u16(0)
```

```
PB = Pin(17,Pin.OUT)
PB = PWM(Pin(17))
PB.freq(100)
PB.duty_u16(0)
```

```
PC = Pin(18,Pin.OUT)
PC = PWM(Pin(18))
PC.freq(100)
PC.duty_u16(0)
```

```
PD = Pin(19,Pin.OUT)
PD = PWM(Pin(19))
PD.freq(100)
PD.duty_u16(0)
```

MicroStepping (cont'd)

A table specifies the PWM signal

- 1/2 wave rectified sine wave
- 0 = 0%
- 65,535 = 100%

Each phase is offset

- A = 0 degree delay
- B = 90 degree delay
- C = 180 degree delay
- D = 270 degree delay

```
TABLE16 = [0, 24874, 45962, 60052, 65000,
60052, 45962, 24874, 0, 0, 0, 0, 0, 0,
0, 0]
```

```
def Step16(X):
    A = TABLE16[X % 16]
    PA.duty_u16(A)
    B = TABLE16[(X+4) % 16]
    PB.duty_u16(B)
    C = TABLE16[(X+8) % 16]
    PC.duty_u16(C)
    D = TABLE16[(X+12) % 16]
    PD.duty_u16(D)
```

```
x = 0
for i in range(0,800):
    x += 1
    Step16(x)
    sleep_ms(5)
```

```
PA.duty_u16(0)
PB.duty_u16(0)
PC.duty_u16(0)
PD.duty_u16(0)
```

MicroStepping with 32 steps per cycle

Use a bigger table and you get finer resolution

- pre-compute $\sin(x)$
- faster program execution

Result is 1600 steps / rotation

- 50×32

No limit on the number of steps per cycle

```
TABLE32 = [0, 12681, 24874, 36112,
45962, 54046, 60052, 63751, 65000,
63751, 60052, 54046, 45962, 36112,
24874, 12681, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0,
0, 0, 0, 0, 0, 0, 0]
```

```
def Step32(X):
    A = TABLE32[X % 32]
    PA.duty_u16(A)
    B = TABLE32[(X+8) % 32]
    PB.duty_u16(B)
    C = TABLE32[(X+16) % 32]
    PC.duty_u16(C)
    D = TABLE32[(X+24) % 32]
    PD.duty_u16(D)
```

```
x = 0
for i in range(0,1600):
    x += 1
    Step32(x)
    sleep_ms(5)
```


```
PA.duty_u16(0)
PB.duty_u16(0)
PC.duty_u16(0)
PD.duty_u16(0)
```

Solenoids

A solenoid is an electromagnet which can either pull or push a rod back and forth. Think of it as an electronic deadbolt:

- When de-energized, the deadbolt locks the door.
- When energized, the deadbolt is pulled back, allowing the door to open.

Since this is an of/off device, a simple binary output from the Pico can be used.



uxcell DC 12V 60N 10mm Stroke Push Pull Type
Open Frame Solenoid Electromagnet XRN-1564T

Visit the uxcell Store

5.0 ★★★★★ 9 ratings

\$25⁴⁹

Get Fast, Free Shipping with Amazon Prime

FREE Returns

Available at a lower price from other sellers that may not offer free Prime shipping.

- **[FEATURE]** - DC 12V 60N Force 10mm Stroke Push Pull Solenoid Electromagnet
- **[GOOD DESIGN]** - Push pull Type, linear motion, open frame, plunger spring return, DC solenoid electromagnet.
- **[ADVANTAGES]** - Simple structure, small volume, high adsorption force.copper coil inside, has good temperature stability and insulation, high eelectrical conductivity
- **[NOTED]** - As an actuating element of anmation equipment ,because the current is large, the single cycle can not be electrified for a long time.The best operate time is in 2 seconds.
- **[APPLICATION]** - DC solenoid electromagnet use in vending machines, transport equipment, office facility household appliance, mechanical, etc game machine,Sorting machine,door lock,etc.

See more product details

Report an issue with this product or seller

Sample Solenoid: Applying 12V to the leads draws 1A and applies 60N of force


Assume for example a uxcell 12V solenoid is to be driven by a Pi-Pico.

To turn on this solenoid, you need:

- $V = 12V$
- $I = 1A @ 12V$

Since a Pi-Pico can't output 12V or 1A directly, add a transistor switch (assume a ZTX1051A NPN transistor).

- Digikey Part: ZTX1051A
- $I_{c(max)} = 4A$
- DC Current Gain (min): 300 @ 1A, 2V
- $V_{ce(sat)} = 210mV @ 1000mA$
- \$0.68 (qty 100)



To saturate the transistor, you need

$$h_{fe} \cdot I_b > I_c$$

$$300 \cdot I_b > 1A$$

$$12mA > I_b > 3.33mA$$

(12mA is the max output of a PiPico)


Rb is then

$$R_b = \left(\frac{3.3V - 0.7V}{I_b} \right)$$

$$217\Omega < R_b < 780\Omega$$

Anything in this range should work.

- Let Rb = 330 Ohms.
- Add a flyback diode to save the transistor
 - inductive load



Solenoid Code:

A simple 1/0 on the output turns the solenoid on and off

Output a 1

- Solenoid turns on
- Lock open

Output a 0

- Solenoid turns off
- Lock closed

```
# Turning a solenoid on and off
from machine import Pin
from time import sleep

GP19 = Pin(19,Pin.OUT)

while(1):
    print('Solenoid On')
    GP19.value(1)
    sleep(1)
    print('Solenoid Off')
    GP19.value(0)
    sleep(1)
```

Brushless DC Motors

Brushless DC motors have become all the rage since about 2010

- quadcopters
- RC cars
- RC aircraft

They're small, inexpensive, and powerful

- \$20 for the one shown
 - includes ESC controller
- 120W (10V @ 12A)

Larger ones are available


- \$29 for 1000W (1.5hp)
- 46 grams



An ESC controller acts as the interface

Inputs:

- Red: +3.3V
- Black: Ground
- White: Control Signal from Pi-Pico




Connections from a Pi-Pico to a BLDC motor.

Controlling the Motor Speed

The control input is a square wave:

- Frequency = 50Hz to 330Hz
- Stop (power on): 0.9ms pulse
- Slow: 1.2ms pulse
- Fast: 3.0ms pulse



The speed of the BLDC motor is set by the pulse width on the Control line

Sample Code

Frequency = 50Hz

- T = 20ms

Startup:

- Pulse-Width = 0.9ms
- Press GP15 button to start

Running:

- slow = 1.2ms
- fast = 3.0ms
- proportional inbetween

```
from machine import Pin
from time import sleep

# GP15 = push button
# GP16 = control input to BLDC

Button = Pin(15, Pin.IN, Pin.PULL_UP)

Control = Pin(16, Pin.OUT)
Control = PWM(Pin(16))
Control.freq(50)

Control.duty_ns(900_000)
while(Button.value() == 1):
    pass

while(1):
    print('slow')
    Control.duty_ns(1_200_000)
    sleep(1)
    print('fast')
    Control.duty_ns(3_000_000)
    sleep(1)
```

Digital Servo Motor

Similar to a BLDC

- Motor is geared down
- Slower output speed
- Higher torque

Two Types:

- Output = Angle (shown)
 - Open / close a valve
 - Turn steering wheels
 - Pan & tilt camera
 - Specify the position of a robotic arm
- Output = Speed
 - 360 degree servo motor
 - Set the speed of an RC car



Digital Servo Motor: Control Input


Similar to a BLDC: 3-wires

- Red: 5.0V to 6.8V, up to 3.0A (varies with the motor)
- Black: Ground
- White: Control Input

The control input controls the output

Example: 270 degree digital servo motor

- Frequency = 50 - 330Hz
- Pulse Width = 500 - 2500us




The pulse width sets the angle of the motor

Digital Servo Motor: Hardware

Wiring a Digital Servo Motor is fairly simple

- You need a common ground
- The Pi-Pico provides the control signal
 - PWM signal
- External power is applied to the red wire



Digital Servo Motor: Code

The code is almost the same as before.

This code has two input buttons

- GP14 decreases the angle
 - pulse width gets smaller
- GP15 increases the angle
 - pulse width gets larger

GP16 is the control input

```
from machine import Pin
from time import sleep_ms

# GP14 = push button (decrease angle)
# GP15 = push button (increase angle)
# GP16 = control input to digital motor

Up = Pin(15, Pin.IN, Pin.PULL_UP)
Down = Pin(14, Pin.IN, Pin.PULL_UP)

Control = Pin(16, Pin.OUT)
Control = PWM(Pin(16))
Control.freq(50)

x = 1_500_000

while(1):
    if(Up.value() == 0):
        x += 1000
    if(Down.value() == 0):
        x -= 1000
    if(x < 500_000):
        x = 500_000
    if(x > 2_500_000):
        x = 2_500_000
    Control.duty_ns(x)
    sleep_ms(1)
```

Continuous Rotation Servo Motor

Used for driving a car, etc

For the example given here:

- Red = 4.8V - 6.0V
- No-Load Current: 100mA
- Stall Current: 550mA
- Pulse Width: 700 - 2300 us
- No-Load Speed: 110 rpm

Price:


- \$15 for two (2024 prices)




Control Signals

The pulse width sets the speed:

- CW: 1500us - 700us
- CCW: 1500us - 2300us
- Stop: 1500us +/- 45us



Wiring to a Pi-Pico is similar to before:



Wiring from a Pi-Pico to a Continuous Servo Motor

Code:

Coding is almost the same

- Button 15: Increase the speed
- Button 14: Decrease the speed
- GP16: Control input

Just set the limits to

- min = 700us
 - reverse fast
- max = 2300us
 - forward fast

```
from machine import Pin
from time import sleep_ms

# GP14 = push button (decrease angle)
# GP15 = push button (increase angle)
# GP16 = control input to motor

Up = Pin(15, Pin.IN, Pin.PULL_UP)
Down = Pin(14, Pin.IN, Pin.PULL_UP)

Control = Pin(16, Pin.OUT)
Control = PWM(Pin(16))
Control.freq(50)

x = 1_500_000

while(1):
    if(Up.value() == 0):
        x += 1000
    if(Down.value() == 0):
        x -= 1000
    if(x < 700_000):
        x = 700_000
    if(x > 2_300_000):
        x = 2_300_000

    Control.duty_ns(x)

    sleep_ms(1)
```

Summary:

Digital motors are pretty easy to interface with a Pi-Pico:

- With a stepper motor, you mimic a 2-phase sine wave with four wires from the Pi-Pico
- With digital servo motors, you control the speed with a pulse width.

Note that these motors are low-power:

- The stepper motor draws 3A @ 5V, meaning 15W
- The digital servo motor draws 2A @ 5V, meaning 10W
- The continuous servo motor draws 550mA @ 5V, meaning 2.7W

Subtract losses in the motors and the power these can deliver is fairly small. If that's all you need, however, these are easy ways to interface motors to a Pi-Pico.
